

Middleby Cooking Systems Group



1400 Toastmaster Drive • Elgin, IL 60120-9272 U. S. A. • Telephone: (847)741-3300 • Service and Parts Fax: (847)741-4406



SUBJECT


Lockout panel removal on Pizza Hut ovens

Fig. 1

GENERAL

This Bulletin serves as notice to Authorized Service Agents that Pizza Hut permits restaurant owners to request the removal of the thumbwheel control lockout plate (see Figure 1).

The lockout plates were installed on ovens produced (or converted) for Pizza Hut prior to the "Lightning Bolt" Oven Readiness program of January 1997. The "Lightning Bolt" program allowed this plate to be removed at the discretion of the restaurant owner. Pizza Hut has informed Middleby Marshall that any plates that were NOT removed during the "Lightning Bolt" program may still be removed, at the restaurant owner's request.



APPLICATION

To remove the lockout plate, remove the two #10 tamper-resistant Torx screws that hold it in place. Discard the Torx screws and the lockout plate. See Figure 1.

COMPATIBILITY

This procedure is compatible with all Middleby Marshall ovens produced or converted for use by Pizza Hut, and that are equipped with a thumbwheel control lockout plate.

FEATURES

N/A

AVAILABILITY

If required, a #10 tamper-resistant Torx screwdriver can be ordered from the Middleby parts department (Middleby P/N 31393).

DISPOSITION OF INVENTORY

N/A