

# Middleby Cooking Systems Group



1400 Toastmaster Drive • Elgin, IL 60120-9272 U. S. A. • Telephone: (847)741-3300 • Service and Parts Fax: (847)741-4406

## Middleby Marshall Service Bulletin

**SUBJECT**

Incorrect Labeling on Conveyor Speed Controller Kits (P/N 37337 - with digital display)

**GENERAL**

Middleby Marshall has found that the new Conveyor Speed Controller Kit with Digital Display, P/N 37337, includes incorrect labeling of the DIP switch settings on the casing. The settings shown for the PS200-series ovens are incorrect.

In addition, the description of the PS555 DIP switch settings is incorrect. Because the PS555 is incorrectly listed with the PS360-series ovens, the time range shown for the PS555 oven is "3-30 min." The PS555 oven should be listing individually, because its correct time range is 4-30 minutes.

The DIP switch settings for all other oven models are correct as shown.

**APPLICATION**

Whenever installing a Speed Controller Kit (P/N 37337) on a PS200-series oven, use the DIP switch guide on this Bulletin instead of the one printed on the casing. Even though controllers produced in the future will have the correct printing on the casing, it may take some time for this new stock to become widespread in the field, so use this Bulletin until further notice.

Whenever installing Kit P/N 37337 on a PS555 oven, note the correct time range of 4-30 minutes. Controllers produced in the future will show this correct information, although it (again) may take some time for the new stock to become available in the field.

