

Middleby Cooking Systems Group



1400 Toastmaster Drive • Elgin, IL 60120-9272 U. S. A. • Telephone: (847)741-3300 • Service and Parts Fax: (847)741-4406

Middleby Marshall® *Service Bulletin*

SUBJECT

End stop and side stop deburring

SUBJECT

Effective immediately, all Authorized Service Agents performing installation, startup, or service on any Middleby Marshall oven should check all edges of the conveyor end stops and side stops. The edges should be deburred or sanded as necessary to remove all sharp edges.

Unless specifically requested by the factory or customer, this procedure should not be the only reason for a service call. It should only be included as part of a normal installation, startup, or service procedure.