

## Middleby Cooking Systems Group



1400 Toastmaster Drive • Elgin, IL 60120-9272 U. S. A. • Telephone: (847)741-3300 • Service and Parts Fax: (847)741-4406

## Middleby Marshall<sup>®</sup> Service Bulletin

### SUBJECT

Availability of rotary switch kits for Middleby ovens - *UPDATE TO MM-188 (8/22/01)*

### GENERAL

Service Bulletin MM-188 (8/22/01) provided a listing of compatible rotary switches and contact blocks for Middleby Marshall ovens. Because of the wide variety of switches that have been used over the years, it has been difficult to ensure that matching switches and contact blocks were always available. To solve this problem, Middleby is now standardizing on ROTARY SWITCH KITS that include the switch and a matching contact block.

At this time, two kits are available:

- **P/N 46521** now includes one Cutler-Hammer rotary switch (P/N 44696) and contact block (P/N 44697). This is now the standard switch kit for all ovens EXCEPT for the combination HEAT/BLOWER switch on PS536 ovens with a 2-switch control panel. Note that this kit has changed from its introduction in Service Bulletin MM-188, because the General Electric switches are no longer available.
- **P/N 46522** now includes one Kit P/N 46521 (described above) and one additional contact block (P/N 46523). It should be used ONLY on the combination HEAT/BLOWER switch on PS536 ovens with a 2-switch control panel. Note that this kit has also changed from its introduction in Service Bulletin MM-188, as it now includes the extra contact block.

### AVAILABILITY

At this time, we request that you begin ordering Kit P/Ns 46521 and 46522 in place of the individual switches and contact blocks.

The General Electric switches described in Service Bulletin MM-188 are no longer available. Note that the original General Electric switch kit, P/N 46521, is now the "standard" Cutler-Hammer switch kit.

### DISPOSITION OF INVENTORY

Any remaining stock of the individual switch components may be used normally.