

Middleby Cooking Systems Group



1400 Toastmaster Drive • Elgin, IL 60120-9272 U. S. A. • Telephone: (847)741-3300 • Service and Parts Fax: (847)741-4406

Middleby Marshall® Service Bulletin

SUBJECT

Update to instructions for PS536 Stacking Hardware Kit, P/N 46494

GENERAL

Service Bulletin MM-194 (11/21/01) announced the PS536 Stacking Hardware Kit, P/N 46494. It has come to the attention of Middleby Technical Service that this Kit has been shipping with incorrect hardware.

The S-hooks including in the kit have a material diameter of approximately 0.12" (3.0mm). This diameter is too small for the weight of one PS536 cavity. *USING THE SUPPLIED S-HOOKS WILL CAUSE THE HOOKS TO BEND OPEN.*

Please replace the S-hooks supplied with your Kit with hooks having a 1/4" (6.4mm) material diameter. These can be purchased at any hardware store.

Remember that proper, *SAFE* stacking of Middleby Marshall ovens is *ESSENTIAL* for any oven installation.

AVAILABILITY

The PS536 Stacking Hardware Kit will not be available from the factory for a short time until the correct hooks can be added to the Kit. Future orders for the Kit will ship with correct hooks.

