

## Middleby Cooking Systems Group



1400 Toastmaster Drive • Elgin, IL 60120-9272 U. S. A. • Telephone: (847)741-3300 • Service and Parts Fax: (847)741-4406



### SUBJECT

This Service Bulletin replaces TM-401. This Bulletin describes the revision of support documents for Model TP44, TP120, and BT120 solid state slot toasters.

### GENERAL

The following documents are released, effective 3/16/99:

- P/N 39297 *Parts Manual, TP44/TP120/BT120, Rev. C, V1*  
Replaces the parts information included in the previous (Rev. B V1) version of this document, and in the *Model TP44/TP120 Owner's Operating Manual* (P/N 3102563).
- P/N 39298 *Update Supplement for TP44/TP120 Owner's Operating Manual, Rev. C, V1*  
Replaces the information included in the previous (Rev. B V1) version of this document. Updates the information in the *Model TP44/TP120 Owner's Operating Manual* (P/N 3102563) to current specifications. Revised material includes new warranty information, warning notices, and wiring diagrams. This supplement will be shipped with all new TP44 and TP120 toasters.
- P/N 39299 *BT120 Supplement for TP44/TP120 Owner's Operating Manual, Rev. C, V1*  
Replaces the information included in the previous (Rev. B V1) version of this document. Updates the *Model TP44/TP120 Owner's Operating Manual* (P/N 3102563) to provide information on the Model BT120 toaster. The new information includes specifications, operating instructions, and wiring diagrams for the BT120. This supplement will be shipped with all new BT120 toasters.

### APPLICATION

- P/N 39297 (Parts Manual) should be used for all TP44, TP120, and BT120 parts information.
- P/Ns 39298 and 39299 (Supplements) should be made available to all personnel who service the affected equipment.

### COMPATIBILITY

- P/N 39297 (Parts Manual) is compatible with Model TP44, TP120, and BT120 toasters.
- P/N 39298 (Update Supplement) is compatible with Model TP44 and TP120 toasters.
- P/N 39299 (BT120 Supplement) is compatible with Model BT120 toasters.

### FEATURES

The revisions described in this Bulletin include information on parts and wiring differences between "A" and "B" versions of these toasters.

### AVAILABILITY

All of these documents are available on the Middleby website, [www.middleby.com](http://www.middleby.com).

### DISPOSITION OF INVENTORY

- Any remaining stock of P/N 3102563, *Model TP44/TP120 Owner's Operating Manual*, should be updated with the supplements as described above.
- Any remaining stock of the Rev. B V1 revisions of P/Ns 38297, 38298, and 39299 should be destroyed.