

Middleby Cooking Systems Group



1400 Toastmaster Drive • Elgin, IL 60120-9272 U. S. A. • Telephone: (847)741-3300 • Service and Parts Fax: (847)741-4406

Middleby Marshall *Service Bulletin*

SUBJECT

Orientation and part numbers of PS555/570/570S blower wheels and cooling fans - REVISED

GENERAL

Service Bulletin MM-183, dated 4/23/01, incorrectly identified the part numbers of the blower wheels on PS570 and PS570S ovens. The illustration included with the bulletin correctly showed the fan blade orientation, and the positioning of the wheels inside the oven; however, the part numbers of the two wheels were reversed.

Also, note that the blower wheels and cooling fans for the PS555 oven are IDENTICAL to those used on current-production PS570S ovens. So, the revised illustration included with this Service Bulletin applies to the PS555 as well.

The part numbers provided in the current Parts Manual for these ovens are correct.


APPLICATION

Please DESTROY the illustration that was FAXed with Service Bulletin MM-183.

Refer to the revised illustration on Page 2 of this Bulletin. File a copy of this new illustration with your PS570/570S Parts Manual and your PS555 Parts Manual. Refer to the illustration when ordering blower wheels or cooling fans for these ovens.

PS555/570/570S Blower Wheel Configuration

PS555 Ovens (All) PS570S Ovens (Current Production)



PS570 Ovens (Original Design)

