

## Middleby Cooking Systems Group



1400 Toastmaster Drive • Elgin, IL 60120-9272 U. S. A. • Telephone: (847)741-3300 • Service and Parts Fax: (847)741-4406

## Middleby Marshall® Service Bulletin

### SUBJECT

New combination gas control valve for CE-approved Middleby Marshall ovens

### GENERAL

Middleby has introduced a new combination gas valve for use on its CE-approved gas ovens. P/N 43085 is manufactured by Honeywell, and is used on the current-production PS555 and PS570 CE oven models. This valve will also be used on PS200-series CE gas ovens beginning in late August 2002.

New Parts Manuals for these ovens showing the change are in progress and will be announced as soon as they are available.


### APPLICATION

- The new Honeywell gas control valve (P/N 43085) should be added to your required parts stocking list.
- The original Dungs gas control valve (P/N 28092-0020) is still in use and should still be stocked.
- When replacing a combination valve in a CE-gas oven, always use the same type of valve that was previously installed. At this time, the new valve (P/N 43085) should not be used to replace the original Dungs valve (P/N 28092-0020).


### AVAILABILITY

P/N 43085 is in stock and available for shipment.

#### Original Dungs valve P/N 28092-0020



#### New Honeywell valve P/N 43085



- Measure manifold pressure at tap in front of burner
- Measure pilot pressure at tap in pilot line