

Middleby Cooking Systems Group



1400 Toastmaster Drive • Elgin, IL 60120-9272 U. S. A. • Telephone: (847)741-3300 • Service and Parts Fax: (847)741-4406

Middleby Marshall® *Service Bulletin*

SUBJECT

Part number correction for PS536 LP orifice (domestic & std. export ovens)

GENERAL

Service Bulletin MM-205-A (6/17/02) incorrectly identified the part number of the PS536 #54 LP orifice as P/N 47310. The correct part number for this orifice is 47320. Please update your records accordingly.

A copy of the original bulletin is attached for your reference. All other information in the Bulletin is still current.